

Id	CLIENT	LOCATION	YEAR	JOB DESCRIPTION
1	Società Padana Energia SpA - Gruppo Gas Plus	Centrale Gas san Potito (RA)	2019-2020	Decommissioning works
2	Colacem	Gubbio (PG)	2018-2020	Sampling and remediation of asbestos-containing material at the Ghigiano (PG) plant
3	Comune di Forli	Forli	2016	Asbestos removal intervention at the Palazzetto dello Sport
4	Cabot Italiana Spa	Ravenna	2016	Removal of asbestos flue at Cabot plant in Ravenna (Italy)
5	Alma Petroli	Ravenna	2015	Sampling to verify the presence of asbestos, safety and remediation of the insulated line section
6	Comune di Forli	Forli	2015	Removal of asbestos and resurfacing at the School of Palmezzano (Forli - Italy)
7	Colacem	Gubbio (PG)	2014-2015	Partial remediation of cooked mills at the Ghigiano plant (PG)
8	Colacem	Gubbio (PG)	2014	Mills cement conglomerate sampling and analysis of cement samples at the Ghigiano plant (PG)
9	Cabot Italiana Spa	Ravenna	2011	Remediation and removal of asbestos from CTE boiler with waste transport and disposal
10	Cabot Italiana Spa	Ravenna	2011	Remediation of dryer containing asbestos with waste transport and disposal
11	Cabot Italiana Spa	Ravenna	2011	Removal of asbestos from equipment and equipment (fans, gaskets, etc ...) with waste transport and disposal
12	Fabbrica del Ghiaccio	Imola (BO)	2003	Asbestos removal, former refrigeration plant insulation with waste transport and disposal.
13	ENI s.p.a.	Ortona	1998-1999	Removal of asbestos roofing in various districts of the DORT with waste transport and disposal - AGIP Ortona district